| Company | | , , | Listing Submitted | 11/19/2018 | Area of state conducts work | |
|---|----------------|---|-----------------------------|------------|--|------------|
| ABC Global Contracting LLC | Р | hone (810) 533-24 | 116 | | Coastal (East of I-95): Yes | |
| 32032 28 Mile Road | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Lenox, Michigan 48048- | | | | | Mountains (West of I-77): Yes | |
| | We | bsite <u>abcglobalco</u> | ntracting.com | | modificants (West of 177). 163 | |
| Comp | oliance Testin | g and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equi | ipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | Yes S | Statistical Iventory Rec | onciliation Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | Yes S | Spill Prevention Equipm | nent Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Γank Tightness Testing | r. | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | JST Internal Inspection | ns (Integrity Assessments): | <u>Yes</u> | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | JST Internal Lining Ins | pections: | <u>Yes</u> | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | Yes (| Other: | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No l | JST Compliance Cons | ultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No l | JST Equipment Verifica | ation: | Yes | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | ı No \ | Naste Disposal and Tre | eatment: | No | | |
| Oil and Solvent Recycling: | | Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 8/4/2020 | Area of state conducts work | |
| Advanced Environmental Services, Inc. | P | hone (336) 282-35 | 586 | | Coastal (East of I-95): Yes | |
| PO Box 38218 | | Fax (336) 282-35 | 587 | | Central (West of I-95 and East of I-77): Yes | |
| Greensboro, NC 27438 | | (000) 202 00 | ,,,, | | | |
| | We | bsite advanceden | vironmental.com | | Mountains (West of I-77): Yes | |
| Comp | pliance Testin | g and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No (| Overfill Prevention Equi | ipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | Statistical Iventory Rec | onciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipm | nent Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No 7 | Tank Tightness Testing | ı: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No l | JST Internal Inspection | ns (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No l | JST Internal Lining Insp | pections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No (| Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Fr | nvironmental | Service Firms | | | Other: | |
| | | | ultante: | No | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | JST Compliance Cons | uitarito. | 110 | | |
| | | JST Compliance Cons JST Equipment Verifica | | No | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | | ation: | No | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes \ | JST Equipment Verifica | ation: | | | |

| Company | | | Listing Submitted | 10/2/2017 | Area of state conducts work | |
|--|--|---|--|----------------------------|--|----------------------------|
| AES of Greenville LLC | 1 | Phone (252) 758-3311 | | | Coastal (East of I-95): Yes | |
| 141 S. Market Street | | Fax (252) 481-5814 | | | Central (West of I-95 and East of I-77): Yes | |
| Washington, NC 27889 | | (202) 101 0011 | | | Mountains (West of I-77): Yes | |
| | We | ebsite www.aes-nc.com | | | wouldains (west of 1-77). Tes | |
| Comp | pliance Testi | ng and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment | Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliati | on Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Te | sting: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integ | grity Assessments): | <u>Yes</u> | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections | s: | <u>Yes</u> | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | | UST System Removal: | <u>Yes</u> |
| Ei | nvironmenta | l Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | . No | Waste Disposal and Treatmen | t: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 10/13/2017 | Area of state conducts work | |
| Apex Engineering, PC | 1 | Phone (301) 417-0200 | | | Coastal (East of I-95): Yes | |
| 15850 Crabbs Branch Way | | Fax (301) 975-0169 | | | Central (West of I-95 and East of I-77): Yes | |
| Suite 200 | | (301) 373 0103 | | | | |
| Rockville, Maryland 20855- | We | ebsite www.apexcos.com | | | Mountains (West of I-77): Yes | |
| Comp | pliance Testi | ng and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | | | | | No |
| Containment Sump Testing: | · - - | Overfill Prevention Equipment | Operability Check: | No | Dispenser Meter Repair/Calibration: | |
| | | Overfill Prevention Equipment Statistical Iventory Reconciliati | | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | | on Services: | | · · · · · · · · · · · · · · · · · · · | |
| | No No | Statistical Iventory Reconciliati | on Services: sting: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No No No | Statistical Iventory Reconciliati Spill Prevention Equipment Te | on Services: sting: | No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No No | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: | on Services: sting: grity Assessments): | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ | on Services: sting: grity Assessments): | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections | on Services: sting: grity Assessments): | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections | on Services: sting: grity Assessments): | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: | on Services: sting: grity Assessments): s: | No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Vo | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: | on Services: sting: grity Assessments): s: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | No No No No No No No No Vo rvironmental Yes Yes | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: I Service Firms UST Compliance Consultants: | on Services: sting: grity Assessments): s: | No No No No No Yes Yes | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No Vo rvironmental Yes Yes Yes | Statistical Iventory Reconciliati Spill Prevention Equipment Te Tank Tightness Testing: UST Internal Inspections (Integ UST Internal Lining Inspections Other: UST Compliance Consultants: UST Equipment Verification: | on Services: sting: grity Assessments): s: | No No No No No | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | | Listing Submitted | 1/3/2020 | Area of state conducts work | |
|--|-----------------|---|----------------------|------------|--|------------|
| CATLIN Engineers and Scientists | Pho | one (910) 452-5861 | | | Coastal (East of I-95): Yes | |
| 220 Old Dairy Road | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Wilmington, NC 28405 | | | | | Mountains (West of I-77): No | |
| | Webs | ite <u>www.CatlinUSA.cor</u> | <u>n</u> | | mountains (West of 177). No | |
| Comp | liance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ov | erfill Prevention Equipment (| Operability Check: N | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Sta | tistical Iventory Reconciliation | on Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | II Prevention Equipment Tes | sting: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | | nk Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | T Internal Inspections (Integ | | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | T Internal Lining Inspections | :: N | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Oth | ner: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | ervice Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> US | T Compliance Consultants: | <u>)</u> | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | Yes US | T Equipment Verification: | N | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> Wa | aste Disposal and Treatment | : <u>\</u> | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Oth | ner: | | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | | |
| Company | | | Listing Submitted | 10/12/2017 | Area of state conducts work | |
| Cobb Environmental & Technical Services, Inc | . Pho | one (662) 841-0995 | | | Coastal (East of I-95): Yes | |
| P. O. Box 1602, Tupelo, MS 38802 | | Fax (662) 841-0810 | | | Central (West of I-95 and East of I-77): Yes | |
| 871 South Green Street | | (002) 011 0010 | | | | |
| Tupelo, MS 38804 | Webs | ite <u>www.cobbenv.com</u> | | | Mountains (West of I-77): Yes | |
| Comp | liance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | Yes Ov | erfill Prevention Equipment (| Operability Check: | <u>res</u> | Dispenser Meter Repair/Calibration: | Yes |
| Containment Sump Testing: | Yes Sta | itistical Iventory Reconciliation | on Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No Spi | III Prevention Equipment Tes | sting: <u>Y</u> | <u>res</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | Yes Tai | nk Tightness Testing: | N | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> US | T Internal Inspections (Integ | rity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> US | T Internal Lining Inspections | s: N | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | Yes Oth | ner: | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | ervice Firms | | | Other: | |
| | | | | <u>Yes</u> | | |
| Emergency Cleanup - Spill/Release: | No US | T Compliance Consultants: | _ | 163 | | |
| | | T Compliance Consultants: T Equipment Verification: | | <u>Yes</u> | | |
| Emergency Cleanup - Spill/Release: | No US | | 7 | | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No US No Wa | T Equipment Verification: | 7 | <u>Yes</u> | | |

| Company | | Listing Submitte | d 11/14/2018 | Area of state conducts work | |
|---|---|--|-------------------------------|--|----------------------------|
| Cohesion, Inc. | Př | none (919) 233-8626 | | Coastal (East of I-95): Yes | |
| 5216 Yates Mill Pond Road Raleigh, NC 27606 | | Fax (919) 233-8909 | | Central (West of I-95 and East of I-77): Yes | |
| | Web | site www.cohesion-inc.com | | Mountains (West of I-77): Yes | |
| Comp | oliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No O | verfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No St | tatistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Sr | oill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Ta | ank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No US | ST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | ST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Ot | ther: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental S | ervice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No U | ST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No US | ST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | aste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No Ot | ther: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitte | d 11/15/2018 | Area of state conducts work | |
| CROMPCO, LLC | Ph | one (800) 646-3161 | | Coastal (East of I-95): Yes | |
| 1815 Gallagher Road | | Fax (610) 278-7621 | | Central (West of I-95 and East of I-77): Yes | |
| Plymouth Meeting, PA 19462 | | | | Mountains (West of I-77): Yes | |
| | Web | site <u>www.crompco.com</u> | | would all s (west of 1-11). | |
| Comp | oliance Testing | and Monitoring | | | |
| Automatic Line Leak Detector Testing: | | and monitoring | | UST Equipmment Service Contractors | |
| | | verfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | Yes O | | Yes Yes | | <u>Yes</u> No |
| Containment Sump Testing: Corrosion Protection Design Experts: | Yes Or Yes St | verfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| | Yes Or Yes St No Sp | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: | <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | Yes Or Yes St No Sp No Ta | verfill Prevention Equipment Operability Check: latistical Iventory Reconciliation Services: bill Prevention Equipment Testing: | <u>Yes</u> <u>Yes</u> | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes Or Yes St No Sp No Ta Yes Us | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: | Yes Yes Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Yes Or Yes St No Sp No Ta Yes Us Yes Us | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): | Yes Yes Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Yes Or Yes St No Sp No Ta Yes Us Yes Us | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: | Yes Yes Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Or Yes St No Sp No Ta Yes US Yes US Yes Or | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: | Yes Yes Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Or Yes St No Sp No Ta Yes Us Yes Or Yes | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: | Yes Yes Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Yes Or Yes St No Sp No Ta Yes Us Yes Or Yes Or Yes Or Yes No Yes No To Yes No Us Yes No Us No Us | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: | Yes Yes Yes No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Yes Or Yes St No Sp No Ta Yes Us Yes Or Yes Or Yes No Us Yes No Us No Us No Us | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants: | Yes Yes No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Or Yes St No Sp No Ta Yes Us Yes Or Yes Or Yes Or No Us No Us No W | verfill Prevention Equipment Operability Check: tatistical Iventory Reconciliation Services: bill Prevention Equipment Testing: ank Tightness Testing: ST Internal Inspections (Integrity Assessments): ST Internal Lining Inspections: ther: Service Firms ST Compliance Consultants: ST Equipment Verification: | Yes Yes No No Yes No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitte | d 8/1/2019 | Area of state conducts work | |
|--|--|---|----------------------------|--|----------------------------|
| D.H. Griffin Wrecking, Inc. | P | Phone (336) 389-3647 | | Coastal (East of I-95): Yes | |
| 4716 Hilltop Road | | Fax (336) 389-3647 | | Central (West of I-95 and East of I-77): Yes | |
| Greensboro, NC 27407 | | (000) 000 00 H | | Mountains (West of I-77): Yes | |
| | We | bsite <u>www.dhgriffin.com</u> | | Wouldains (West Of 1-77). Tes | |
| Comp | oliance Testin | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No (| Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No l | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No l | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No (| Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No l | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | ا No | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | Yes (| Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitte | d 6/20/2018 | Area of state conducts work | |
| DAVENPORT | F | Phone (910) 251-8912 | | Coastal (East of I-95): Yes | |
| 3722 Shipyard Boulevard | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Suite E | | I dx | | | |
| Wilmington, NC 28412 | We | bsite http://www.davenportworld.com/ | | Mountains (West of I-77): Yes | |
| Comp | oliance Testin | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | | | | |
| Containment Comm. Testings | No (| Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No No | | No No |
| Corrosion Protection Design Experts: | No S | | | Dispenser Meter Repair/Calibration: | |
| _ | No S | Statistical Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S No S No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No S No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No S No S No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No S No S No No No No | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S No S No No N | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S No S No No N | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No S | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No S | Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitted | | Area of state conducts work | |
|---|---------------------------------|---|------------|--|------------|
| East Carolina Petroleum Services Inc | | Phone (252) 339-3655 | | Coastal (East of I-95): Yes | |
| PO Box 1923 | | Fax (252) 331-2754 | | Central (West of I-95 and East of I-77): No | |
| 510 W Broad Street | | (202) 001 2701 | | Mountains (West of I-77): No | |
| Elizabeth City, NC 27909 | W | ebsite ecpetro.com | | Mountains (West of 1-77). No | |
| Comp | pliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | <u>Yes</u> |
| Ei | nvironmenta | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | . No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 5/26/2020 | Area of state conducts work | |
| East Coast Environmental PA | | Phone (919) 772-0268 | | Coastal (East of I-95): Yes | |
| 3815 Junction Boulevard | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27603 | | | | Mountains (West of I-77): No | |
| | W | ebsite <u>eastcoastenv.com</u> | | Moditalis (West of 1-77). No | |
| Comp | pliance Testi | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| | | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No | Other: | | oo i i ping/oump motamation. | |
| Leak Detection Monitoring Services: Line Tightness Testing: | No No | Other: | | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: | No | Other: Service Firms | | | <u>Yes</u> |
| Line Tightness Testing: | No nvironmenta | | Yes | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: | No nvironmenta | Service Firms | Yes Yes | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: Energency Cleanup - Spill/Release: | No nvironmenta Yes Yes | Service Firms UST Compliance Consultants: | | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No nvironmenta Yes Yes | UST Compliance Consultants: UST Equipment Verification: | <u>Yes</u> | UST System Removal: | <u>Yes</u> |

| Company | | | Listing Submitted | 10/18/2017 | Area of state conducts work | |
|---|--|--|-------------------|---|---|----------------------|
| Enviro Consulting | | Phone (704) 721-0101 | - | | Coastal (East of I-95): Yes | |
| 531 Pitts School Road NW | | Fax (704) 721-0102 | | | Central (West of I-95 and East of I-77): Yes | |
| Suite D | | (101) 121 0102 | | | Mountains (West of I-77): Yes | |
| Concord, NC 28027 | V | /ebsite www.envirocorp.net | | | Mountains (West of 1-77): Tes | |
| Comp | pliance Test | ting and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Ope | erability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation | Services: | <u>Yes</u> | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | <u>Yes</u> | Spill Prevention Equipment Testin | g: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity | Assessments): | <u>Yes</u> | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | | <u>Yes</u> | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | UST Lining Insta | allation | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | | UST System Removal: | <u>Yes</u> |
| E | nvironmenta | al Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | | No | | |
| Oil and Solvent Recycling: | No | Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
| Environmental Contracting & Consulting Serv | ices, P | Phone (757) 912-2276 | | | Coastal (East of I-95): Yes | |
| 10 3rd Avenue | | Fax | | | Central (West of I-95 and East of I-77): No | |
| Southern Shores, NC 27949 | | | | | Mountains (West of I-77): No | |
| | V | /ebsite | | | mountains (west of 1-77). No | |
| Comp | pliance Test | ing and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Ope | erability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | and the second s | | | Look Detection Equipment Installation, Conditions | No |
| | No | Statistical Iventory Reconciliation | Services: | No | Leak Detection Equipment Installation Servicing: | |
| Corrosion Protection Design Experts: | No No | Statistical Iventory Reconciliation Spill Prevention Equipment Testin | | No No | Spill Bucket Installation Repair: | No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | | | | | | No No |
| | No | Spill Prevention Equipment Testin | g: | No | Spill Bucket Installation Repair: | |
| Corrosion Protection System Repairs: | No No | Spill Prevention Equipment Testin Tank Tightness Testing: | g: | No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: | No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity | g: | No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: | g: | No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: | g: | No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other: | g: | No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other: | g: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: | No No No No No No Vo revironment: Yes Yes | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: | g: | No No No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No Vo revironment: Yes Yes | Spill Prevention Equipment Testin Tank Tightness Testing: UST Internal Inspections (Integrity UST Internal Lining Inspections: Other: al Service Firms UST Compliance Consultants: UST Equipment Verification: Waste Disposal and Treatment: | g: | No No No No Yes Yes Yes | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |

| Company | | | Listing Su | bmitted | 8/4/2020 | Area of state conducts work | |
|--|-------------------------------|------------|--|----------------|----------------|--|------------|
| Environmental Laboratories, Inc | | Phone | (864) 370-0637 | | | Coastal (East of I-95): Yes | S |
| PO Box 1729 | | Fax | (864) 752-0948 | | | Central (West of I-95 and East of I-77): Yes | S |
| Travelers Rest, SC 29609 | | | , | | | Mountains (West of I-77): Yes | |
| | 1 | Nebsite | www.elabsinc.net | | | mountains (west of 177). Too | 5 |
| Comp | oliance Tes | ting and | Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill | Prevention Equipment Operability Che | eck: Ye | es es | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistic | cal Iventory Reconciliation Services: | N | 0 | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Pro | evention Equipment Testing: | <u>Ye</u> | <u>es</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Ti | ightness Testing: | <u>Ye</u> | <u>es</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Int | ternal Inspections (Integrity Assessmen | nts): <u>Y</u> | <u>es</u> | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Int | ternal Lining Inspections: | <u>Y</u> | <u>es</u> | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | <u>Yes</u> | | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironment | tal Servi | ce Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Co | ompliance Consultants: | <u>Y</u> (| <u>es</u> | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Ed | quipment Verification: | N | 0 | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste | Disposal and Treatment: | N | 0 | | |
| Oil and Solvent Recycling: | No | Other: | | | | | |
| Soil and Water Testing Lab: | No | | | | | | |
| Company | | | Listing Su | bmitted | 5/7/2018 | Area of state conducts work | |
| Environmental Restorations LLC | | Phone | (919) 855-9082 | | | Coastal (East of I-95): Yes | S |
| 328 Shipwash Drive | | Fax | (919) 855-9083 | | | Central (West of I-95 and East of I-77): Yes | S |
| Garner, NC 27529 | | | | | | Mountains (West of I-77): No | |
| | <u> </u> | Nebsite | www.erllc.com | | | , | |
| Comp | oliance Tes | ting and | Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill | Prevention Equipment Operability Che | eck: No | 0 | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistic | cal Iventory Reconciliation Services: | Ne | 0 | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Pro | evention Equipment Testing: | Ne | 0 | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | | ightness Testing: | Ne | 0 | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | | ternal Inspections (Integrity Assessmen | nts): N | 0 | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Int | ternal Lining Inspections: | N | 0 | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | | | UST Piping/Sump Installation: | No |
| | | | | | | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: | No | | | | | | |
| | | tal Servic | ce Firms | | | Other: REME | DIATION |
| | No | | ce Firms ompliance Consultants: | Y | es | Other: REME | DIATION |
| Er | No nvironment | UST Co | | Y. | | Other: REME | DIATION |
| Emergency Cleanup - Spill/Release: | No nvironment Yes No | UST Co | ompliance Consultants: | N | | Other: REME | DIATION |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No nvironment Yes No | UST Co | ompliance Consultants: quipment Verification: | N | 0 <u>es</u> | Other: REME | DIATION |

| Company | | 31 List (7 lii) - 33 | Listing Submitted | 11/15/2018 | Area of state conducts work | |
|--|----------------|---|---------------------|------------|--|------------|
| EnviroTrac Ltd. | P | hone (336) 763-6025 | | | Coastal (East of I-95): Yes | |
| 7343 West Friendly Avenue | | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Greensboro, NC 27410 | | | | | Mountains (West of I-77): Yes | |
| | Web | osite <u>www.envirotrac.com</u> | <u>m</u> | | wouldens (west of 1-77). Tes | |
| Comp | oliance Testin | g and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | Overfill Prevention Equipment | Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | tatistical Iventory Reconciliati | on Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | | pill Prevention Equipment Te | sting: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | IST Internal Inspections (Integ | | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No L | IST Internal Lining Inspection | S: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No C | Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes L | IST Compliance Consultants: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | Yes L | IST Equipment Verification: | | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes V | Vaste Disposal and Treatmen | t: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No C | Other: | | | | |
| Soil and Water Testing Lab: | <u>Yes</u> | | | | | |
| Company | | | Listing Submitted | 11/16/2018 | Area of state conducts work | |
| Evo Corporation | P | hone (336) 725-5844 | | | Coastal (East of I-95): Yes | |
| 1703 Vargrave Street | | Fax (336) 725-6244 | | | Central (West of I-95 and East of I-77): Yes | |
| Winston-Salem, NC 27107 | | , | | | Mountains (West of I-77): Yes | |
| | Web | osite <u>www.evocorp.net</u> | | | mountains (west of 177). | |
| Comp | oliance Testin | g and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No C | Overfill Prevention Equipment | Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | tatistical Iventory Reconciliati | ion Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | pill Prevention Equipment Te | sting: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No L | IST Internal Inspections (Integ | grity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No L | IST Internal Lining Inspection | s: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No C | Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service Firms | | | Other: | |
| | | 107.0 | | No | | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | IST Compliance Consultants: | | | | |
| | | IST Compliance Consultants: IST Equipment Verification: | | No | | |
| Emergency Cleanup - Spill/Release: | No L | | | | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No U | IST Equipment Verification: | | No | | |

| Company | o i iovidor i | Listing Submitted | 8/4/2020 | Area of state conducts work | |
|---|--|---|----------------------------|---|----------------------------|
| Fourstar Petroleum | Phone | (540) 563-1022 | | Coastal (East of I-95): Yes | |
| 1119 Beaumont Rd. | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| Roanoke, VA 24019 | Website | www.fourstarpetro.com | | Mountains (West of I-77): Yes | |
| Comp | oliance Testing an | d Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | Il Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | Yes |
| Containment Sump Testing: | | ical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | Yes |
| Corrosion Protection Design Experts: | No Spill P | revention Equipment Testing: | No | Spill Bucket Installation Repair: | Yes |
| Corrosion Protection System Repairs: | | Fightness Testing: | No | UST Equipment Installation - Other: | Yes |
| Corrosion Protection System Testing: | No UST I | nternal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No UST I | nternal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No Other: | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Serv | ice Firms | | Other: Wayne Dispensers and Verifor | ne POS |
| Emergency Cleanup - Spill/Release: | No UST C | Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No UST E | Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No Other: | | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 11/9/2018 | Area of state conducts work | |
| Geo-Hydro Engineers, Inc. | Phone | (704) 837-7174 | | Coastal (East of I-95): Yes | |
| 2748 Interstate Street | | | | | |
| 1 | Fax | (| | · · · · · · · · · · · · · · · · · · · | |
| Suite A | Fax | (| | Central (West of I-95 and East of I-77): Yes | |
| | Fax Website | | | · · · · · · · · · · · · · · · · · · · | |
| Suite A Charlotte, NC 28208 | | www.geohydro.com | | Central (West of I-95 and East of I-77): Yes | |
| Suite A Charlotte, NC 28208 | Website | www.geohydro.com | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | No |
| Suite A Charlotte, NC 28208 Comp | Website Dliance Testing an No Overfi | www.geohydro.com d Monitoring | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors | No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: | Website bliance Testing an No Overfi No Statist | www.geohydro.com d Monitoring Il Prevention Equipment Operability Check: | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | Website Dliance Testing an No Overfii No Statist No Spill P | www.geohydro.com d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Website Dliance Testing an No Overfi No Statist No Spill P No Tank | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: trevention Equipment Testing: | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | Website Diance Testing an No Overfi No Statist No Spill P No Tank | www.geohydro.com d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Fightness Testing: | No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Website Diance Testing an No Overfi No Statist No Spill P No Tank | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Tightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Website Diance Testing an No Overfii No Statist No Spill P No Tank No UST II No UST II | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Tightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Website Diance Testing an No Overfi No Statist No Spill P No Tank No UST II No Other: | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Fightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Website pliance Testing an No Overfi No Statist No Spill P No Tank No UST II No UST II No Other: No | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Fightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er | Website Diance Testing an No Overfi No Statist No Spill P No Tank No UST II No UST II No Other: No Divironmental Serv | d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: Prevention Equipment Testing: Fightness Testing: Internal Inspections (Integrity Assessments): Internal Lining Inspections: ice Firms | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Suite A Charlotte, NC 28208 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | Website Diance Testing an No Overfi No Statist No Spill P No Tank No UST II No UST II No Other: No nvironmental Serv Yes UST E | www.geohydro.com d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: drevention Equipment Testing: Fightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: ice Firms Compliance Consultants: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Suite A Charlotte, NC 28208 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Website Diance Testing an No Overfi No Statist No Spill P No Tank No UST II No UST II No Other: No Torironmental Serv No UST O Yes UST E | www.geohydro.com d Monitoring Il Prevention Equipment Operability Check: ical Iventory Reconciliation Services: revention Equipment Testing: Tightness Testing: internal Inspections (Integrity Assessments): internal Lining Inspections: ice Firms Compliance Consultants: Equipment Verification: E Disposal and Treatment: | No No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | | Listing Submitted | 11/14/2018 | Area of state conducts work | |
|--|---|---|---|--------------------------|--|----------------------------|
| Geological Resources, Inc. | F | hone | (704) 845-4010 | | Coastal (East of I-95): Yes | |
| 3502 Hayes Road | | Fax | (704) 845-4012 | | Central (West of I-95 and East of I-77): Yes | |
| Monroe, NC 28110 | | | (***)******* | | Mountains (West of I-77): Yes | |
| | We | ebsite | www.geologicalresourcesinc.com | | mountains (west of 177). Tes | |
| Comp | pliance Testir | ng and | Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill | Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistic | cal Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Pro | evention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Ti | ghtness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Int | ternal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Int | ternal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental | Service | ce Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Co | ompliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Ec | quipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes ' | Waste I | Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 11/29/2018 | Area of state conducts work | |
| GREENWOOD APPLIED SERVICES LLC | F | Phone | (252) 398-6022 | | Coastal (East of I-95): Yes | |
| P.O. BOX 238 | | Fax | (252) 356-2208 | | Central (West of I-95 and East of I-77): No | |
| COLERAIN, NC 27924 | | | | | Mountains (West of I-77): No | |
| | We | ebsite | www.greenwoodapplied.com | | | |
| Comp | | | | | | |
| | pliance Testir | ng and | Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | | Monitoring Prevention Equipment Operability Check: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No | Overfill | | No No | | No No |
| | No No | Overfill Statistic | Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Containment Sump Testing: | No No No | Overfill Statistic Spill Pre | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Containment Sump Testing: Corrosion Protection Design Experts: | No No No | Overfill Statistic Spill Pre Tank Ti | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No No | Overfill Statistic Spill Pre Tank Ti UST Int | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: | No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No | Overfill Statistic Spill Pre Tank Ti UST Int | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No | Overfill Statistic Spill Pre Tank Ti UST Int UST Int | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No | Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: Servic UST Co | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No N | Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: Servic UST Cc UST Eq | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms ompliance Consultants: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No No No No voironmental Yes No No | Overfill Statistic Spill Pre Tank Ti UST Int UST Int Other: Servic UST Cc UST Eq | Prevention Equipment Operability Check: cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ternal Inspections (Integrity Assessments): ternal Lining Inspections: ce Firms ompliance Consultants: quipment Verification: | No No No No No No No Yes | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitte | | Area of state conducts work | |
|--|---|---|----------------------------|--|--|
| Guardian Fueling Technologies | Pi | hone (919) 729-6980 | | Coastal (East of I-95): Yes | |
| 5116 Departure Drive | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27616 | | | | Mountains (West of I-77): Yes | |
| | Web | osite <u>www.guardianfueltech.com</u> | | | |
| Comp | oliance Testing | g and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> O | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> S | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No S | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No T | ank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No U | JST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> U | JST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> O | Other: SafeGuard UST Inspectio | n Services | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental S | Service Firms | | Other: FuelGuard Fuel Cleaning & Biocide Tr | eatment |
| Emergency Cleanup - Spill/Release: | No U | JST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No U | JST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | ı No 🛚 V | Vaste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No O | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitte | ed 11/14/2018 | Area of state conducts work | |
| HARCO Services LLC | Pi | hone (770) 917-8846 | | Coastal (East of I-95): Yes | |
| PO Box 2347 | | Fax (770) 917-0921 | | Central (West of I-95 and East of I-77): Yes | |
| Kennesaw, GA 30156 | | (, | | Mountains (West of I-77): Yes | |
| | Web | osite www.harcoservices.com | | Wouldains (West of 1-77). Tes | |
| Comp | | | | | |
| • | oliance Testing | g and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | g and Monitoring Overfill Prevention Equipment Operability Check: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | No |
| _ | No O | | No No | · · · | No No |
| Automatic Line Leak Detector Testing: | No O | Overfill Prevention Equipment Operability Check: | | Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No O No S No S | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No O No S No S No T | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No O No S No S No T No U | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: | No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No O No S No S No T No U No U | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No O No S No S No T No U No U | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: JST Internal Inspections (Integrity Assessments): JST Internal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No <u>Yes</u> |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No O No S No S No T No U No O | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No <u>Yes</u> No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No O No S No S No T No U No O | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No <u>Yes</u> No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No O No S No S No T No U No O No O No O No O Invironmental \$ No U | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No <u>Yes</u> No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No O No S No S No T No U No O | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No <u>Yes</u> No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No O No S No S No T No U No O No O No O O O O O O O O O O O O O O O O O O O | Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Fank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No <u>Yes</u> No |

| Company | | Listing Submitted | 11/14/2018 | Area of state conducts work | |
|--|-------------------|---|------------------|---|------------|
| Highlands Environmental Solutions, Inc. | Pho | ne (919) 848-3155 | | Coastal (East of I-95): Yes | |
| 8410-D Falls of Neuse Road | | ax (919) 848-4265 | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27615 | • | (0.0) 0.0 | | Mountains (West of I-77): Yes | |
| | Websi | te <u>www.HESfast.com</u> | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testing a | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ove | erfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Stat | tistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spil | I Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tan | k Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No UST | Γ Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST | Γ Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Oth | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | rvice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | Yes US | Γ Compliance Consultants: | Yes | | |
| Environmental Engineer/Geologist - Site Checks: | | Γ Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | ste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No Oth | | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 8/18/2020 | Area of state conducts work | |
| Company | Pho | | 0/10/2020 | | |
| Law Petroleum, Inc. 11025 Arlington Church Road | Pho | , | | Coastal (East of I-95): Yes | |
| Charlotte, NC 28227 | F | ax (704) 573-3535 | | Central (West of I-95 and East of I-77): Yes | |
| | Websi | ite | | Mountains (West of I-77): Yes | |
| Comr | oliance Testing a | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | erfill Prevention Equipment Operability Check: | Yes | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | istical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | |
| Corrosion Protection Design Experts: | | I Prevention Equipment Testing: | | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection Design Expens. Corrosion Protection System Repairs: | | k Tightness Testing: | <u>Yes</u> | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Repairs. Corrosion Protection System Testing: | | Γ Internal Inspections (Integrity Assessments): | <u>Yes</u> | | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | | Γ Internal Lining Inspections: | <u>Yes</u> | UST Equipment Repair: UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Equipment Operability Check. Leak Detection Monitoring Services: | | | <u>Yes</u> | UST Piping/Sump Installation: | Yes Yes |
| | | с і. | | UST System Removal: | <u>Yes</u> |
| Line Tightness Testing: | Yes | | | Other: | <u>Yes</u> |
| | nvironmental Se | | | Outer. | |
| | Voc IIC | Γ Compliance Consultants: | <u>Yes</u> | | |
| Emergency Cleanup - Spill/Release: | | | | | |
| Environmental Engineer/Geologist - Site Checks: | No UST | Γ Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: Environmental Engineer/Geologist Soil and GW Cleanu | No UST | ste Disposal and Treatment: | <u>Yes</u> No | | |
| Environmental Engineer/Geologist - Site Checks: | No UST | ste Disposal and Treatment: | | | |

| Company | | Listing Submitted | 8/3/2020 | Area of state conducts work | |
|---|--|---|-----------------------------------|---|----------------------------|
| MECO, Inc. of Florence | | Phone (910) 223-0018 | | Coastal (East of I-95): Yes | |
| 316 Raymond Street | | Fax (910) 223-0022 | | Central (West of I-95 and East of I-77): Yes | |
| Fayetteville, NC 28301 | | (0.0) = 0.0 | | Mountains (West of I-77): No | |
| | W | ebsite <u>www.mecoflorence.com</u> | | mountains (west of 177). No | |
| Comp | oliance Testi | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | <u>Yes</u> | Other: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmenta | Il Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 1/3/2020 | Area of state conducts work | |
| MGF Environmental, PLLC | | Phone (904) 814-3680 | | Coastal (East of I-95): No | |
| 288 Gap Creek Rd. | | | | | |
| | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Fletcher, NC 28732 | | | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | |
| Fletcher, NC 28732 | W | Fax bttp://www.mgfenvironmental.com | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | |
| | | | | | |
| | | ebsite http://www.mgfenvironmental.com | No | Mountains (West of I-77): Yes | No |
| Сотр | oliance Testi | rebsite http://www.mgfenvironmental.com ing and Monitoring | No No | Mountains (West of I-77): Yes UST Equipmment Service Contractors | No No |
| Comp Automatic Line Leak Detector Testing: | oliance Testi No | rebsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: | | Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | debsite http://www.mgfenvironmental.com ing and Monitoring http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: | No No | Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: | No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No No No No No No | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No No No No | ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No N | ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No N | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Il Service Firms UST Compliance Consultants: | No No No No No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | debsite http://www.mgfenvironmental.com ing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | No No No No Ves No | Wountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submitted | | Area of state conducts work | |
|---|--|--|--------------------------------|---|--------------------------|
| Mineral Springs Environmental | | Phone (919) 266-8186 | | Coastal (East of I-95): Yes | |
| 4600 Mineral Springs Lane | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Raleigh, NC 27616 | | | | Mountains (West of I-77): Yes | |
| | W | ebsite | | mountains (West of 1-77). Tes | |
| Comp | oliance Test | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmenta | I Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | <u>Yes</u> | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 11/20/2018 | Area of state conducts work | |
| Petroleum Equipment and Service, Inc. | | Phone (704) 335-8801 | | Coastal (East of I-95): Yes | |
| 4125 Sinclair Street | | Fax (704) 342-1672 | | Central (West of I-95 and East of I-77): Yes | |
| PO Box 1949 | | (101) 012 1012 | | | |
| Denver, NC 28037 | W | ebsite <u>www.petroleumequipment.net</u> | | Mountains (West of I-77): Yes | |
| Comp | oliance Test | ing and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | NIa | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| | | Statistical rectiony recommends of Services. | No | 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1 | |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | Yes | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | | | | | <u>Yes</u> <u>Yes</u> |
| | No | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No | Spill Prevention Equipment Testing: Tank Tightness Testing: | <u>Yes</u> <u>Yes</u> | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | <u>Yes</u> |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | <u>Yes</u> <u>Yes</u> No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | <u>Yes</u> <u>Yes</u> |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No <u>Yes</u> | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | <u>Yes</u> <u>Yes</u> No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No <u>Yes</u> <u>Yes</u> | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | <u>Yes</u> <u>Yes</u> No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No <u>Yes</u> <u>Yes</u> | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | <u>Yes</u> <u>Yes</u> No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No Yes Yes Yes | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: | No No Yes Yes Yes nvironmenta No No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: | Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes |
| Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Er Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No Yes Yes Yes nvironmenta No No | Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: UST Compliance Consultants: UST Equipment Verification: | Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes Yes Yes |

| Company | | ` ' | | 11/14/2018 | Area of state conducts work | |
|--|------------------------|--|-------------------|------------|--|------------|
| Petroleum Equipment Service of Wilson, Inc. | Ph | one (252) 237-6047 | | | Coastal (East of I-95): Yes | |
| P.O. Box 502 | | Fax (252) 237-5507 | | | Central (West of I-95 and East of I-77): Yes | |
| 711 S. Goldsboro St. | | (202) 201 0001 | | | Mountains (West of I-77): No | |
| Wilson, NC 27894 | Webs | site <u>www.peswilson.com</u> | | | Mountains (west of 1-77): No | |
| Comp | oliance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | verfill Prevention Equipment Op | | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | Yes St | atistical Iventory Reconciliation | Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No Sp | ill Prevention Equipment Testin | ng: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No Ta | ink Tightness Testing: | | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No US | ST Internal Inspections (Integrity | y Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | Yes US | ST Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No Ot | her: | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | | UST System Removal: | No |
| Er | nvironmental S | ervice Firms | | | Other: | |
| Emergency Cleanup - Spill/Release: | No US | ST Compliance Consultants: | | No | | |
| Environmental Engineer/Geologist - Site Checks: | No US | ST Equipment Verification: | | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No W | aste Disposal and Treatment: | | No | | |
| Oil and Solvent Recycling: | No Ot | her: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 8/18/2020 | Area of state conducts work | |
| Petroleum Service & Calibration, Inc. | Ph | one (704) 489-1671 | | | Coastal (East of I-95): Yes | |
| 7973 Vista View Drive | | Fax (704) 489-1672 | | | Central (West of I-95 and East of I-77): Yes | |
| Sherrills Ford, NC 28673 | | | | | Mountains (West of I-77): No | |
| | Webs | site <u>www.petroleumtankte</u> | sting.com | | mountains (west of 1-17). No | |
| Comp | oliance Testing | and Monitoring | | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | Yes O | verfill Prevention Equipment Op | erability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | Yes St | atistical Iventory Reconciliation | Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No Sp | ill Prevention Equipment Testir | ng: | <u>Yes</u> | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | | ink Tightness Testing: | | <u>Yes</u> | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | Yes US | ST Internal Inspections (Integrity | y Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | Yes US | ST Internal Lining Inspections: | | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | <u>Yes</u> Ot | her: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | | UST System Removal: | No |
| | | ervice Firms | | | Other: | |
| Er | nvironmental S | | | | | |
| Emergency Cleanup - Spill/Release: | | ST Compliance Consultants: | | No | | |
| | No US | | | No No | | |
| Emergency Cleanup - Spill/Release: | No US | ST Compliance Consultants: | | | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No US No US No W | ST Compliance Consultants: ST Equipment Verification: | | No | | |

| Company | o i iovido | Listing Submitted | | Area of state conducts work | |
|--|--|---|--------------------------------------|---|------------------------------------|
| Petroleum Solutions Inc. | Pho | one (919) 605-1979 | | Coastal (East of I-95): Yes | |
| 3012 Whitehart Ln. | | Fax (919) 773-1704 | | Central (West of I-95 and East of I-77): Yes | |
| 819 Purser Drive | | (616) 116 1161 | | Mountains (West of I-77): No | |
| Raleigh, NC 27606 | Webs | ite <u>www.petroleumsolutionsinc.net</u> | | Wouldains (West of 1-77). No | |
| Comp | oliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ov | erfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | Yes Sta | tistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spi | Il Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No Tai | nk Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | | T Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | No US | T Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No Oth | ner: | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | ervice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No US | T Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No US | T Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No Wa | ste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No Oth | ner: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 3/19/2018 | Area of state conducts work | |
| PetroTest Inc. | Pho | one (919) 902-3794 | | Coastal (East of I-95): Yes | |
| | | (010) 002 0101 | | oodstal (Edst of 199). Tes | |
| 7 Dawn Rd. | | , | | | |
| 7 Dawn Rd. Benson, NC 27504 | 1 | =ax | | Central (West of I-95 and East of I-77): Yes | |
| | Webs | Fax | | | |
| Benson, NC 27504 | | ite www.petrotest.net | | Central (West of I-95 and East of I-77): Yes | |
| Benson, NC 27504 | Webs | ite www.petrotest.net | <u>Yes</u> | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | No |
| Benson, NC 27504 | Webs Dliance Testing Yes Ov | ite <u>www.petrotest.net</u> and Monitoring | Yes No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors | No <u>Yes</u> |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: | Webs bliance Testing Yes Ov Yes Sta | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | Webs pliance Testing Yes Ov Yes Sta No Spi | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Webs pliance Testing Yes Ov Yes Sta No Spi No Tai | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: | No <u>Yes</u> | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | <u>Yes</u> <u>Yes</u> |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Webs Dliance Testing Yes Ov Yes Sta No Spi No Tai Yes US | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: | No <u>Yes</u> <u>Yes</u> | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | <u>Yes</u> <u>Yes</u> No |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | Webs Dliance Testing Yes Ov Yes Sta No Spi No Tai Yes US | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | Yes Yes No No |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | Webs pliance Testing Yes Ov Yes Sta No Spi No Tai Yes US Yes US | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | No <u>Yes</u> <u>Yes</u> No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | Yes Yes No No No |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Webs pliance Testing Yes Ov. Yes Sta No Spi No Tai Yes US Yes US Yes Oth | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner: | No <u>Yes</u> <u>Yes</u> No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | Yes Yes No No No No |
| Benson, NC 27504 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Webs pliance Testing Yes Ov. Yes Sta No Spi No Tai Yes US Yes US Yes Oth Yes Oth Yes | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner: | No <u>Yes</u> <u>Yes</u> No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes No No No No |
| Benson, NC 27504 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | Webs pliance Testing Yes Over Yes State No Spin No Tait Yes US Yes US Yes Oth Yes Oth Yes No US | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner: | No Yes Yes No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes No No No No |
| Benson, NC 27504 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | Webs pliance Testing Yes Over Yes Start No Spirit No Tail Yes US Yes US Yes US Yes Other Yes No US No US No US | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner: ervice Firms T Compliance Consultants: | No Yes Yes No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes No No No No |
| Comparison, NC 27504 Rutomatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Webs pliance Testing Yes Over Yes State No Spino Tail Yes US Yes US Yes Off Yes No US No US No US No Wa | ite www.petrotest.net and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ner: ervice Firms T Compliance Consultants: T Equipment Verification: | No Yes Yes No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | Yes Yes No No No No |

| Company | | Listing Submitted | 11/14/2018 | Area of state conducts work | |
|--|---------------------|--|-------------------|--|------------|
| PGP Services, LLC | P | Phone (704) 619-1528 | | Coastal (East of I-95): Yes | |
| 1949 Candlewick Drive | | Fax (803) 802-2441 | | Central (West of I-95 and East of I-77): Yes | |
| Fort Mill, SC 29715 | | | | Mountains (West of I-77): Yes | |
| | We | bsite | | mountains (west of 177). | |
| Comp | oliance Testin | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | <u>Yes</u> | Overfill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | <u>Yes</u> | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | <u>Yes</u> | Spill Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | <u>Yes</u> | Tank Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | <u>Yes</u> | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | <u>Yes</u> | | | UST System Removal: | <u>Yes</u> |
| E | nvironmental | Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | <u>Yes</u> | UST Equipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes | Waste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 7/30/2020 | Area of state conducts work | |
| Pilot Geological, PLLC | P | Phone (336) 310-4527 | | Coastal (East of I-95): Yes | |
| 743 Park Lawn Court | | Fax (336) 310-4527 | | Central (West of I-95 and East of I-77): Yes | |
| PO 128 | | (655) 655 1521 | | Mountains (West of I-77): Yes | |
| Kernersville, NC 27285 | We | bsite <u>www.pilotenviro.com</u> | | Mountains (West of 1-77): Tes | |
| Comp | oliance Testin | ng and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No : | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| | | | | Other: | |
| | | Service Firms | | | |
| | nvironmental | Service Firms UST Compliance Consultants: | <u>Yes</u> | | |
| E | nvironmental Yes | | | | |
| Emergency Cleanup - Spill/Release: | Yes Yes | UST Compliance Consultants: | Yes Yes Yes | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | Yes Yes Yes | UST Compliance Consultants: UST Equipment Verification: | <u>Yes</u> | | |

| | | Listing Submitted | 11/8/2019 | Area of state conducts work | |
|--|--|---|---|--|---|
| | Phone (910) 790-8265 | | | Coastal (East of I-95): Yes | |
| | Fax | | | Central (West of I-95 and East of I-77): Yes | |
| | | | | | |
| V | lebsite www.oil-tank.com | | | meantaine (voor et 117). He | |
| oliance Test | ing and Monitoring | | | UST Equipmment Service Contractors | |
| No | Overfill Prevention Equipmen | t Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| No | Statistical Iventory Reconcilia | ition Services: | No | Leak Detection Equipment Installation Servicing: | No |
| No | Spill Prevention Equipment T | esting: | No | Spill Bucket Installation Repair: | No |
| No | Tank Tightness Testing: | | No | UST Equipment Installation - Other: | No |
| No | UST Internal Inspections (Inte | egrity Assessments): | No | UST Equipment Repair: | No |
| No | UST Internal Lining Inspectio | ns: | No | UST System Installation - Complete Systems: | No |
| No | Other: | | | UST Piping/Sump Installation: | No |
| No | | | | UST System Removal: | <u>Yes</u> |
| nvironment | al Service Firms | | | Other: | |
| Yes | UST Compliance Consultants | 3: | Yes | | |
| | UST Equipment Verification: | | No | | |
| | Waste Disposal and Treatme | ent: | No | | |
| No | Other: | | uations | | |
| <u>Yes</u> | | | | | |
| | | Listing Submitted | 11/29/2018 | Area of state conducts work | |
| | Phone (704) 892-8600 | | | | |
| | • • • | | | | |
| | Fax (104) 092-0111 | | | | |
| V | lebsite precisiontankserv | ice.com | | Mountains (West of I-77): Yes | |
| oliance Test | ing and Monitoring | | | UST Equipmment Service Contractors | |
| | | t Operability Check: | Yes | | Yes |
| | | | | = 10 p = 110 c = 110 c = 110 p | |
| Yes | Statistical Iventory Reconcilia | tion Services: | | Leak Detection Equipment Installation Servicing: | No |
| <u>Yes</u> No | Statistical Iventory Reconcilia Spill Prevention Equipment T | | <u>Yes</u> | Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| No | Spill Prevention Equipment T | | <u>Yes</u> <u>Yes</u> | Spill Bucket Installation Repair: | No |
| No No | Spill Prevention Equipment T Tank Tightness Testing: | esting: | <u>Yes</u> <u>Yes</u> <u>Yes</u> | Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No |
| No No <u>Yes</u> | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte | egrity Assessments): | Yes Yes Yes No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No |
| No No <u>Yes</u> <u>Yes</u> | Spill Prevention Equipment T Tank Tightness Testing: | egrity Assessments): | <u>Yes</u> <u>Yes</u> <u>Yes</u> | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| No No <u>Yes</u> | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection | egrity Assessments): | Yes Yes Yes No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No |
| No No <u>Yes</u> <u>Yes</u> <u>Yes</u> | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: | egrity Assessments): | Yes Yes Yes No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| No No <u>Yes</u> <u>Yes</u> <u>Yes</u> <u>Yes</u> | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: | egrity Assessments): ns: | Yes Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| No No Yes Yes Yes Yes Yes No | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: | egrity Assessments): ns: | Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| No No Yes Yes Yes Yes Yes No No | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: al Service Firms UST Compliance Consultants UST Equipment Verification: | egrity Assessments): ns: | Yes Yes No No Yes No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| No No Yes Yes Yes Yes Yes No | Spill Prevention Equipment T Tank Tightness Testing: UST Internal Inspections (Inte UST Internal Lining Inspection Other: | egrity Assessments): ns: | Yes Yes No No | Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| r | No N | Website www.oil-tank.com Diance Testing and Monitoring No Overfill Prevention Equipment No Statistical Iventory Reconcilia No Spill Prevention Equipment To No Tank Tightness Testing: No UST Internal Inspections (Internal Lining Inspection No Other: No Diance Testing Waste Disposal and Treatme No Other: Yes Waste Disposal and Treatme No Other: Yes Phone (704) 892-8600 Fax (704) 892-8711 Website precisiontankservi | Phone (910) 790-8265 Fax Website www.oil-tank.com Diance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No Statistical Iventory Reconciliation Services: No Spill Prevention Equipment Testing: No Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No Other: No Divironmental Service Firms Yes UST Compliance Consultants: Yes UST Equipment Verification: Yes Waste Disposal and Treatment: No Other: Oil Tank Eval Yes Listing Submitted Phone (704) 892-8600 Fax (704) 892-8711 Website precisiontankservice.com | Phone (910) 790-8265 Fax Website www.oil-tank.com Diance Testing and Monitoring No Overfill Prevention Equipment Operability Check: No No Statistical Iventory Reconciliation Services: No No Spill Prevention Equipment Testing: No No Tank Tightness Testing: No No UST Internal Inspections (Integrity Assessments): No No UST Internal Lining Inspections: No No Other: No No Other: No No Other: No No UST Compliance Consultants: Yes Yes UST Compliance Consultants: No No Other: No No Other: No N | Phone (910) 790-8265 Fax Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com Website www.oil-tank.com West of I-95 and East of I-77): Yes Mountains (West of I-77): No West of I-77): No UST Equipment Service Contractors No Spill Prevention Equipment Operability Check: No No Spill Prevention Equipment Testing: No No I Tank Tightness Testing: No UST Internal Inspections (Integrity Assessments): No UST Internal Lining Inspections: No UST Internal Lining Inspections: No Other: No Other: No West of I-77): Yes West of I-77): Yes Website precisiontankservice.com Coastal (East of I-95): Yes Central (West of I-95) and East of I-77): Yes Website precisiontankservice.com Coastal (East of I-95): Yes Central (West of I-95) and East of I-77): Yes Mountains (West of I-77): Yes Mountains (West of I-77): Yes Website precisiontankservice.com UST Equipment Service Contractors |

| Company | o i iovidoi | Listing Submitted | 11/15/2018 | Area of state conducts work | |
|--|--------------------|---|------------|--|------------|
| Progress Environmental Group, Inc. | Phon | e (336) 722-9999 | | Coastal (East of I-95): Yes | |
| 120 Fayette Street | Fa | | | Central (West of I-95 and East of I-77): Yes | |
| Winston-Salem, NC 27101 | 1 4 | (555) . 22 5555 | | Mountains (West of I-77): Yes | |
| | Website | www.progressenvironmental.com | | Wouldains (West of 1-77). Tes | |
| Comp | oliance Testing an | nd Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Overf | ill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Statis | tical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spill F | Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tank | Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No UST I | Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Other | : | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Serv | vice Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No UST | Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | Yes UST I | Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes Waste | e Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | Yes Other | | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitted | 11/15/2018 | Area of state conducts work | |
| Protective Technologies, Inc. | Phon | e (803) 424-0412 | | Coastal (East of I-95): Yes | |
| 711 Mill Street | Fa | x (803) 424-0414 | | Central (West of I-95 and East of I-77): Yes | |
| Camden, SC 29020 | | (555) 12 1 5 1 1 1 | | Mountains (West of I-77): Yes | |
| | Website | www.protectivetechnologiesinc.com | | Mountains (West of 1-77): Tes | |
| Comp | oliance Testing an | nd Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Overf | ill Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | Yes Statis | tical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spill F | Prevention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | Yes Tank | Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | Yes UST I | Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | Yes UST I | Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No Other | : | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | No |
| Er | nvironmental Serv | vice Firms | | Other: | |
| | No UST (| Compliance Consultants: | <u>Yes</u> | | |
| Emergency Cleanup - Spill/Release: | | | | | |
| Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | | Equipment Verification: | No | | |
| | No UST I | Equipment Verification: e Disposal and Treatment: | No No | | |
| Environmental Engineer/Geologist - Site Checks: | No UST I | e Disposal and Treatment: | | | |

| Company | | Listing Submitte | d 11/15/2018 | Area of state conducts work | |
|--|--|---|----------------------------|---|----------------------------|
| RES, Inc | | Phone (252) 809-3608 | | Coastal (East of I-95): Yes | |
| PO Bob 402 | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| 3593 Wild Cat Road | | | | Mountains (West of I-77): No | |
| Williamston, NC 27892 | | Website | | wountains (west of 1-11). No | |
| Comp | oliance T | esting and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No | Statistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No | Spill Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Tightness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | No | UST Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No | UST Internal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No | Other: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironm | ental Service Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | No | Waste Disposal and Treatment: | <u>Yes</u> | | |
| Oil and Solvent Recycling: | No | Other: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submitte | d 11/19/2018 | Area of state conducts work | |
| B (0 !) 0 | | | | | |
| Royster Oil Company, Inc. | | Phone (704) 487-6344 | | Coastal (East of I-95): No | |
| PO Box 1467 | | , , | | | |
| PO Box 1467 720 S Lafayette St | | | | Central (West of I-95 and East of I-77): Yes | |
| PO Box 1467 | | , , | | | |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 | oliance T | Fax (704) 487-7811 | | Central (West of I-95 and East of I-77): Yes | |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 | <mark>oliance T</mark> No | Fax (704) 487-7811 Website www.roysteroil.com | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes | No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 | | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors | No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: | No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: | | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: | No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: | No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Compa Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No No No No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comp Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No No No No | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: | No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No N | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Tental Service Firms UST Compliance Consultants: | No No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| PO Box 1467 720 S Lafayette St Shelby, NC 28150 Comparison Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No N | Fax (704) 487-7811 Website www.roysteroil.com Testing and Monitoring Overfill Prevention Equipment Operability Check: Statistical Iventory Reconciliation Services: Spill Prevention Equipment Testing: Tank Tightness Testing: UST Internal Inspections (Integrity Assessments): UST Internal Lining Inspections: Other: Tental Service Firms UST Compliance Consultants: UST Equipment Verification: | No No No No No | Central (West of I-95 and East of I-77): Yes Mountains (West of I-77): Yes UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | | Listing Submitted | | Area of state conducts work | |
|--|---|---|---|-----------------------------------|--|----------------------------|
| Singleton Environmental, Inc. | P | hone | (828) 667-5001 | | Coastal (East of I-95): No | |
| PO Box 2012 | | Fax | (828) 667-0105 | | Central (West of I-95 and East of I-77): No | |
| 1301 Sand Hill Road | | I ux | (020) 007 0100 | | Mountains (West of I-77): Yes | |
| Enka, NC 28728 | We | bsite | www.singletonenvironmental.com | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testin | ng and | Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No (| Overfill | Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No S | Statistic | al Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No S | Spill Pre | evention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No | Tank Ti | ghtness Testing: | No | UST Equipment Installation - Other: | No |
| Corrosion Protection System Testing: | | | ernal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No l | UST Int | ernal Lining Inspections: | No | UST System Installation - Complete Systems: | No |
| Leak Detection Monitoring Services: | No (| Other: | | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| Eı | nvironmental | Service | e Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | <u>Yes</u> | UST Co | mpliance Consultants: | <u>Yes</u> | | |
| Environmental Engineer/Geologist - Site Checks: | Yes | UST Eq | uipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | Yes \ | Waste [| Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No (| Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 11/14/2018 | Area of state conducts work | |
| Terracon Consultants, Inc. | P | hone | (704) 509-1777 | | Coastal (East of I-95): Yes | |
| 2701 Westport Road | | Fax | (704) 509-1888 | | Central (West of I-95 and East of I-77): Yes | |
| Charlotte, NC 28208 | | | | | | |
| | | | | | Mountains (West of I-77): Yes | |
| I. | We | bsite | www.terracon.com | | Mountains (West of I-77): Yes | |
| Comp | We pliance Testin | | | | UST Equipmment Service Contractors | |
| Comparing Line Leak Detector Testing: | pliance Testin | ng and | | No | · , | No |
| | pliance Testin | ng and Overfill | Monitoring | No No | UST Equipmment Service Contractors | No No |
| Automatic Line Leak Detector Testing: | No S | ng and Overfill Statistic | Monitoring Prevention Equipment Operability Check: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No S | ng and Overfill Statistic Spill Pre | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No S No S No S No S | ng and Overfill Statistic Spill Pre Tank Tig | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: | No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No S | ng and Overfill Statistic Spill Pre Tank Tig | Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No Control | ng and Overfill Statistic Spill Pre Tank Tig | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No Control | ng and Overfill Statistic Spill Pre Tank Tig UST Int | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S | overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: | Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S | Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: | Monitoring Prevention Equipment Operability Check: all Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No S | Overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En Emergency Cleanup - Spill/Release: | No S | overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co UST Eq | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: EE Firms Impliance Consultants: | No No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No S | overfill Statistic Spill Pre Tank Tig UST Int UST Int Other: Servic UST Co UST Eq | Monitoring Prevention Equipment Operability Check: al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: EE Firms Impliance Consultants: uipment Verification: | No No No No Ves No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | 70 1 10 110 | | Listing Submitted | 11/20/2018 | Area of state conducts work | |
|--|---|--|---|----------------------------|--|----------------------------|
| TideLand Construction, LLC | F | Phone | (252) 524-1644 | | Coastal (East of I-95): Yes | |
| 3600 North Drive | | Fax | (252) 565-8724 | | Central (West of I-95 and East of I-77): Yes | |
| Greenville, NC 27834- | | | , | | Mountains (West of I-77): Yes | |
| | We | ebsite | tidelandconstruction.com | | meantaine (treet et 177). Tee | |
| Comp | pliance Testir | ng and | Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No | Overfill | Prevention Equipment Operability Check: | <u>Yes</u> | Dispenser Meter Repair/Calibration: | <u>Yes</u> |
| Containment Sump Testing: | <u>Yes</u> | Statistic | al Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | <u>Yes</u> |
| Corrosion Protection Design Experts: | No | Spill Pre | evention Equipment Testing: | <u>Yes</u> | Spill Bucket Installation Repair: | <u>Yes</u> |
| Corrosion Protection System Repairs: | No | Tank Ti | ghtness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No | UST Int | ernal Inspections (Integrity Assessments): | No | UST Equipment Repair: | <u>Yes</u> |
| Leak Detection Equipment Operability Check: | <u>Yes</u> | UST Int | ernal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No | Other: | | | UST Piping/Sump Installation: | <u>Yes</u> |
| Line Tightness Testing: | No | | | | UST System Removal: | <u>Yes</u> |
| E | nvironmental | l Servic | e Firms | | Other: | |
| Emergency Cleanup - Spill/Release: | No | UST Co | mpliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No | UST Eq | uipment Verification: | <u>Yes</u> | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | ı No | Waste [| Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No | Other: | | | | |
| Soil and Water Testing Lab: | No | | | | | |
| Company | | | Listing Submitted | 5/22/2018 | Area of state conducts work | |
| Vistabution LLC | F | Phone | (919) 844-9375 | | Coastal (East of I-95): Yes | |
| 8315 Six Forks Rd | | Fax | (919) 861-0849 | | Central (West of I-95 and East of I-77): Yes | |
| Suite 205 | | I ux | (0.10) 00.1 00.10 | | | |
| Raleigh, NC 27615 | We | ebsite | www.vistabution.com | | Mountains (West of I-77): Yes | |
| Comp | pliance Testir | ng and | Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | | | | | | |
| Containment Sump Testing: | No | Overfill | Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | | | Prevention Equipment Operability Check: al Iventory Reconciliation Services: | No No | | No No |
| Corrosion Protection Design Experts: | No | Statistic | | | Dispenser Meter Repair/Calibration: | |
| | No No | Statistic Spill Pre | al Iventory Reconciliation Services: | No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No No No | Statistic Spill Pre Tank Tig | al Iventory Reconciliation Services: evention Equipment Testing: | No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No No No | Statistic Spill Pre Tank Tig UST Inte | al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: | No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No No No No | Statistic Spill Pre Tank Tig UST Inte | eal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No No No No | Statistic Spill Pre Tank Tig UST Into UST Into | eal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No No No No No | Statistic Spill Pre Tank Tig UST Into UST Into Other: | al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No | Statistic Spill Pre Tank Tig UST Into UST Into Other: | al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Tronmental Yes | Statistic Spill Pre Tank Tig UST Into UST Into Other: | al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: | No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: | No No No No No No No Vo nvironmental Yes Yes | Statistic Spill Pre Tank Tiq UST Into UST Into Other: | cal Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: ce Firms empliance Consultants: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Emergency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No No No No No No No vironmental Yes Yes Yes | Statistic Spill Pre Tank Tiq UST Into UST Into Other: | al Iventory Reconciliation Services: evention Equipment Testing: ghtness Testing: ernal Inspections (Integrity Assessments): ernal Lining Inspections: ce Firms empliance Consultants: uipment Verification: | No No No No No | Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |

| Company | | Listing Submi | itted 9/6/2018 | Area of state conducts work | |
|--|--|---|-----------------------------------|--|----------------------------|
| Vital Fuel Systems, Inc. | Pho | one (919) 303-7374 | | Coastal (East of I-95): Yes | |
| 1076 Classic Road | F | Fax (919) 303-7399 | | Central (West of I-95 and East of I-77): Yes | |
| Apex, NC 27539 | _ | (0.13) 000 1000 | | Mountains (West of I-77): Yes | |
| | Webs | ite <u>www.vitalfuelsystems.com</u> | | Mountains (West of 1-77). Tes | |
| Comp | oliance Testing | and Monitoring | | UST Equipmment Service Contractors | |
| Automatic Line Leak Detector Testing: | No Ove | erfill Prevention Equipment Operability Check: | No | Dispenser Meter Repair/Calibration: | No |
| Containment Sump Testing: | No Sta | tistical Iventory Reconciliation Services: | No | Leak Detection Equipment Installation Servicing: | No |
| Corrosion Protection Design Experts: | No Spil | Il Prevention Equipment Testing: | No | Spill Bucket Installation Repair: | No |
| Corrosion Protection System Repairs: | No Tan | nk Tightness Testing: | No | UST Equipment Installation - Other: | <u>Yes</u> |
| Corrosion Protection System Testing: | No US | T Internal Inspections (Integrity Assessments): | No | UST Equipment Repair: | No |
| Leak Detection Equipment Operability Check: | No US | T Internal Lining Inspections: | No | UST System Installation - Complete Systems: | <u>Yes</u> |
| Leak Detection Monitoring Services: | No Oth | er: | | UST Piping/Sump Installation: | No |
| Line Tightness Testing: | No | | | UST System Removal: | <u>Yes</u> |
| Er | nvironmental Se | rvice Firms | | Other: loval, Upgrades. We do not work at retail fueling | ıg sites. |
| Emergency Cleanup - Spill/Release: | No US | T Compliance Consultants: | No | | |
| Environmental Engineer/Geologist - Site Checks: | No US | T Equipment Verification: | No | | |
| Environmental Engineer/Geologist Soil and GW Cleanu | | ste Disposal and Treatment: | No | | |
| Oil and Solvent Recycling: | No Oth | er: | | | |
| Soil and Water Testing Lab: | No | | | | |
| Company | | Listing Submi | itted 8/13/2020 | Area of state conducts work | |
| WithersRavenel, Inc. | Pho | one (919) 469-3340 | | Coastal (East of I-95): Yes | |
| 115 MacKenan Drive | | Fax | | Central (West of I-95 and East of I-77): Yes | |
| Cary, NC 27511 | | ax . | | Central (West of 1-35 and Last of 1-11). Tes | |
| | | | | Maria (1915 - 19 | |
| | Webs | ite <u>www.withersravenel.com</u> | | Mountains (West of I-77): Yes | |
| Сотр | Webs | | | Mountains (West of I-77): Yes UST Equipmment Service Contractors | |
| Comp Automatic Line Leak Detector Testing: | oliance Testing | | No | . , | No |
| _ | No Ove | and Monitoring | No No | UST Equipmment Service Contractors | No No |
| Automatic Line Leak Detector Testing: | No Ove No Sta | and Monitoring erfill Prevention Equipment Operability Check: | | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: | |
| Automatic Line Leak Detector Testing: Containment Sump Testing: | No Ove No Sta No Spil | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: | No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: | No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: | No Ove No Star No Spi No Tar | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: | No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: | No Ove No Sta No Spi No Tar No US | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: | No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: | No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: | No Ove No Sta No Spi No Tar No US | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: | No Ove No Sta No Spil No Tar No US' No US' | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: | No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Ove No Sta No Spil No Tan No US' No US' No Oth | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Ove No Sta No Spi No Tan No US No US No Oth No Oth | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ter: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: En | No Ove No Sta No Spi No Tan No US No US No Oth No O | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: nk Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: Ervice Firms T Compliance Consultants: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: | No Ove No Sta No Spi No Tar No US No US No Oth No Oth No Tes Sta | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: ter: | No No No No Yes No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |
| Automatic Line Leak Detector Testing: Containment Sump Testing: Corrosion Protection Design Experts: Corrosion Protection System Repairs: Corrosion Protection System Testing: Leak Detection Equipment Operability Check: Leak Detection Monitoring Services: Line Tightness Testing: Energency Cleanup - Spill/Release: Environmental Engineer/Geologist - Site Checks: | No Ove No Sta No Spi No Tan No US No US No Oth No Oth No Tes See US Yes US | and Monitoring erfill Prevention Equipment Operability Check: tistical Iventory Reconciliation Services: Il Prevention Equipment Testing: ak Tightness Testing: T Internal Inspections (Integrity Assessments): T Internal Lining Inspections: er: ervice Firms T Compliance Consultants: T Equipment Verification: ste Disposal and Treatment: | No No No No | UST Equipmment Service Contractors Dispenser Meter Repair/Calibration: Leak Detection Equipment Installation Servicing: Spill Bucket Installation Repair: UST Equipment Installation - Other: UST Equipment Repair: UST System Installation - Complete Systems: UST Piping/Sump Installation: UST System Removal: | No No No No No |